

April 16, 2019 SP 1904798:1 Coliform Bacteria Analysis

Meadowlark Ranches Mutual Water Co.

Attn: Mike Hadley System Number: 4200612

P.O. Box 606 **Project Name** : Routine Bacteriological Santa Ynez, CA 93460-0606

Analytical Results

Customer ID

: 2021676

ID	Sample Description	Total	Fecal E. Coli		Units	Method	Prep	Footnote
1	SS at White Oak	Absent		Absent	A/P/100ml	SM 9223B	Colilert-P/A 18	

N/R Not Required MPN Most Probable Number A/P Absence/Presence

The samples listed above were Acceptable for both Total and Fecal Coliform

Sample Handling Information

ID	Sample Number	System Number	Sample Type/Reason	Sampler	Employed By	Sampled
1	SP 1904798-001	4200612	System-Routine	Matthew Jimenez	FGL Environmental	2019-04-10 09:00

Field Analysis/QA Information

ID	Sample Description	Cl Total/Free mg/l	Temp	Analysis Started	Analysis Completed	Contact	Contacted
1	SS at White Oak	/1.07		2019-04-10 15:27 lkb	2019-04-11 12:38 lkb	N/R	

Analyses were performed at the FGL Santa Paula Laboratory using Standard Methods 20th edition. If you have any questions regarding your results, please call. The FGL Santa Paula Laboratory is certified by California ELAP #1573 and accredited to ISO/IEC 17025:2005 by PJLA certificate #75605, Testing.

Prepared By: SMH

cc:SBCEH

Digitally signed by Raquel R. Harve Reviewed and Raquel R. Harvey [10] Title: Tech Director Microbiology Date: 2019-04-16 Approved By



Monthly

CHAIN OF CUSTODY www.fglinc.com Laboratory Copy (1 of 3)

	1677:04/15/2019				Γ	TEST DESCRIPTION -			oo Boyona	aido for C			ative and Sampling information L215		
Client: Meadowlark Ranches Mutual Water Co. Address: Attn: Mike Hadley P.O. Box 606 Santa Ynez, CA 93460-0606						TEST DES	CKII	11014 - 3	CC REVEISE	side for C	ontainer, i	reservati	e and Sam	pling information	L215
Turbiase Graci Manison.	ite(C) Grab(G)	**SEE REVERSE SIDE** le(NP) Ag Water(AgW)	Source(SR) Waste(W)	Repeat(RPT) Replace	Coliform - Colilert-P/A 120ml(PBa)-Na2S2O3	Field Test-Field CI Free	Sampling Fee								
	ling:	Type of Sample **SEE R Potable(P) Non-Potable(NP)	Other(O) System(Bacti Reason: Routhe(ROUT) Repeat(RPT) Replace(RPL) Other(O) Special(SPL)											
Num Location Description Sampled Sampled 1 SS at White Oak 4 10 1 9 20	_	DW S	T A	ÃÕ	12 Cc	1.07	X S								
Remarks:	Relind	uished			Date:	Time:	Rei	inquished		Date:	Ti	me: Re	linquished	Date:	Time:
(/)	M	ed By:	γ		10 19 Date:	1415 Time:	Rec	eived By:		Date:			ceived By:	Date:	Time:

Corporate Offices & Laboratory 853 Corporation Street

Santa Paula, CA 93060 Phone: (805) 392-2000

Env Fax: (805) 525-4172 / Ag Fax: (805) 392-2063

Office & Laboratory 2500 Stagecoach Road

Stockton, CA 95215 Phone: (209) 942-0182 Fax: (209) 942-0423

Office & Laboratory

563 E. Lindo Chico, CA 95926 Phone: (530) 343-5818 Fax: (530) 343-3807

Office & Laboratory 3442 Empresa Drive, Suite D San Luis Obispo, CA 93401 Phone: (805) 783-2940

Fax: (805) 783-2912

Office & Laboratory 9415 W. Goshen Avenue Visalia, CA 93291 Phone: (559) 734-9473 Fax: (559) 734-8435